

Name : Wijil Pustiko

Date of birth : Binjai, June 26, 1968

Nationality : Indonesian Civil Status : Married Religion : Moslem

Language Capability : Indonesian and English

Language Profeciency

LanguageSpeakingWritingReadingIndonesianGoodGoodGoodEnglishGoodGoodGood

Educational Background

## Politeknik Mechanical of National University, Lhokseumawe

## Training/Course

- 1. Non Destructive Test Level 1 B4T, 1991
- 2. Ultrasonic Level II, 1992
- 3. Achievment Motivation Training, 1992
- 4. Crane Inspector Depnaker, 1992
- 5. Welding Inspector, 1994
- 6. Eddy Current Level I, 1996
- 7. Eddy Current Level II, 1997
- 8. Interpretation Document for ISO 2000, 1997
- 9. Audit Mutu Internal, 1998
- 10. Pressure Vessel Inspector Migas, 1998
- 11. Project Management, 1999
- 12. Performance Management, 2000
- 13. Statistic Process Control, 2000
- 14. Active Communication & Human Relation, 2000
- 15. Crane Inspector Migas 2002
- 16. Piping Inspector, Migas 2002
- 17. Storage Tank Operator Migas, 2004
- 18. Inspektur bejana tekan Migas, 2004
- 19. Account Manager Development Program, 2004
- 20. Basic Sea Suvival, 2005
- 21. Helicopter Under water Escape Training, 2005
- 22. Basic fire figthing, 2005
- 23. Basic First Aid Training, 2005
- 24. Account Manager Development Program II, 2005
- 25. Advance Supervisory Management, 2005
- 26. Personal Power, 2006
- 27. Internal Quality Audit, 2007
- 28. Workshop Project Management For Engineering, 2007
- 29. High Impact Presentation, 2009
- 30. Manajemen Operasi dan Proses Produksi, 2010
- 31. Sucsessful Account Partner Training, 2012
- 32. Petrolium Engineering for Non Engineers 2012
- 33. Manajemen Operasi dan Proses Produksi, 2012
- 34. Inspektur Bejana Tekan Migas 2013
- 35. Inspektur Pesawat Angkat Migas, 2014
- 36. Audit Internal SNI ISO/IEC 17020:2012, 2017
- 37. Pelatihan kopetensi Kelistrikan, 2017
- 38. Inspektur Pesawat Angkat Migas, 2017
- 39. Pelatihan Studi Kelayakan Bisnis dan investasi, 2017

				With Sucofindo
*	Since 1991			
				Present Position
*	Inspector			
*	Managerial			
				Country of Work Experience
<b>*</b>	Indonesia	*	China	
*	Malaysia	*	Swiss	
*	Jepang	*	Singapure	
*	Korea	*	Thailand	
				Profesional Experience

# 1991 PT. Arun NGL Co, Lhokseumawe

Position: Inspector

Inspection and Recertification Pressure Vessel

- Wijil Pustiko

Responsible for: Visual Inspection

Cont'd Curriculum Vitae

Review Material Test Report

Verifying that the Manufacturer has a valid Certificate of Authorization and is working to a Quality Control System

Verifying that the aplicable design calculations are available

Verifying that materials used in the construction of the vessel comply with the requirement

Verifying that all welding and brazing procedures have been qualified

Making Visual Inspection of Vessel to confirm that there are no material or dimensional defects

Performing External and Internal inspections and witnessing the hydrostatic or pneumatic test.

Verifying that the required marking is provided and that any nameplate has been attached to the proper vessel.

Reporting all inspection during and after finishing the job.

## 1992 : PT. Arun NGL Co, Lhokseumawe

Position : Inspector

Inspection and Recertification Pressure Vessel

#### Responsible for:

- Visual Inspection
- Review Material Test Report
- Verifying that the Manufacturer has a valid Certificate of Authorization and is working to a Quality Control System
- Verifying that the aplicable design calculations are available
- Verifying that materials used in the construction of the vessel comply with the requirement
- Verifying that all welding and brazing procedurres have been qualified
- Making Visual Inspection of Vessel to confirm that there are no material or dimensional defects
- Performing External and Internal inspections and witnessing the hydrostatic or pneumatic test.
- Verifying that the required marking is provided and that any nameplate has been attached to the proper vessel.
- Reporting all inspection during and after finishing the job.

Cont'd Curriculum Vitae - Wijil Pustiko

# Mobil Oil Indonesia Inc., Lhokseumawe

Position : Inspector

Inspection and Recertification Pressure Vessel

# Responsible for:

- Visual Inspection
- Review Material Test Report
- Verifying that the Manufacturer has a valid Certificate of Authorization and is working to a Quality Control System
- Verifying that the aplicable design calculations are available
- Verifying that materials used in the construction of the vessel comply with the requirement
- Verifying that all welding and brazing procedurres have been qualified
- Making Visual Inspection of Vessel to confirm that there are no material or dimensional defects
- Performing External and Internal inspections and witnessing the hydrostatic or pneumatic test.
- Verifying that the required marking is provided and that any nameplate has been attached to the proper vessel.
- Reporting all inspection during and after finishing the job.

## PT. Arun NGL Co, Lhokseumawe

Position : Inspector

Eddy Current Test of Heat exchanger Tube

#### Responsible for:

- Perform Eddy Current Test
- Evaluate and report the result

## PT. Asean Aceh Fertilizer, Lhokseumawe

Position: Inspector

Inspection and Recertification Pressure Vessel

# Responsible for:

- Visual Inspection
- Review Material Test Report
- Verifying that the Manufacturer has a valid Certificate of Authorization and is working to a Quality Control System
- Verifying that the aplicable design calculations are available
- Verifying that materials used in the construction of the vessel comply with the requirement
- Verifying that all welding and brazing procedurres have been qualified
- Making Visual Inspection of Vessel to confirm that there are no material or dimensional defects
- Performing External and Internal inspections and witnessing the hydrostatic or pneumatic test.
- Verifying that the required marking is provided and that any nameplate has been attached to the proper vessel.
- Reporting all inspection during and after finishing the job.

## 1993 : PT. Arun NGL Co, Lhokseumawe

Position : Inspector

Inspection and Recertification Pressure Vessel

## Responsible for:

- Visual Inspection
- Review Material Test Report
- Verifying that the Manufacturer has a valid Certificate of Authorization and is working to a Quality Control System
- Verifying that the aplicable design calculations are available
- Verifying that materials used in the construction of the vessel comply with the requirement

Cont'd Curriculum Vitae - Wijil Pustiko

- Verifying that all welding and brazing procedures have been qualified
- Making Visual Inspection of Vessel to confirm that there are no material or dimensional defects
- Performing External and Internal inspections and witnessing the hydrostatic or pneumatic test.

- Verifying that the required marking is provided and that any nameplate has been attached to the proper vessel.
- Reporting all inspection during and after finishing the job.

# PT. Arun NGL Co, Lhokseumawe

Position: Inspector Coordinator Inspection and Rigging Hardware

# Responsible for:

- Visual Inspection
- Review NDT reports
- Witnessed NDT
- Evaluate and report the result

# 1994 : Mobil Oil Indonesia Inc., Lhokseumawe

Position : Inspector

Inspection and Recertification Pressure Safety Valve

## Responsible for:

- Visual Inspection
- Review supporting document
- Witnessed function test
- Evaluate and report the result

## PT. Arun NGL Co, Lhokseumawe

Position: Inspector

Eddy Current Test of Heat exchanger Tube

# Responsible for:

- Perform Eddy Current Test
- Evaluate and report the result

## 1995 : PT. Arun NGL Co, Lhokseumawe

Position : Inspector

Inspection and Recertification Pressure Vessel

# Responsible for:

- Visual Inspection
- Review Material Test Report
- Verifying that the Manufacturer has a valid Certificate of Authorization and is working to a Quality Control System
- Verifying that the aplicable design calculations are available
- Verifying that materials used in the construction of the vessel comply with the requirement
- Verifying that all welding and brazing procedurres have been qualified
- Making Visual Inspection of Vessel to confirm that there are no material or dimensional defects
- Performing External and Internal inspections and witnessing the hydrostatic or pneumatic test.
- Verifying that the required marking is provided and that any nameplate has been attached to the proper vessel.
- Reporting all inspection during and after finishing the job.

Cont'd Curriculum Vitae - Wijil Pustiko

## Mobil Oil Indonesia Inc., Lhokseumawe

Position: Welding Inspector

Inspection and Quality Control piping at Arun Booster Compression

- Visual Inspection
- Review NDT reports
- Witnessed NDT
- Evaluate and report the result

# PT. Lasmo Oil, Pekanbaru

Position : Inspector

Inspection and certification Crane

# Responsible for:

- Visual Inspection
- Review NDT reports
- Witnessed NDT
- Witness Load Test
- Evaluate and report the result

## PT. Total Indonesia, Balik Papan

Position : Inspector Ultrasonic Inspection

# Responsible for:

- Visual Inspection
- Review NDT reports
- Witnessed NDT
- Evaluate and report the result

# 1996 : Mobil Oil Indonesia Inc., Lhokseumawe

Position: Welding Inspector

Inspection and Maintenance at various Project

## Responsible for:

- Visual Inspection
- Review NDT reports
- Witnessed NDT
- Evaluate and report the result

## Mobil Oil Indonesia Inc., Lhokseumawe

Position: Welding Inspector

Inspection of Rotating Equipment at Cluster A.

## Responsible for:

- Visual Inspection
- Review NDT reports
- Witnessed NDT
- Function Test
- Evaluate and report the result

# 1997 : Mobil Oil Indonesia Inc., Lhokseumawe

Position: Welding Inspector

Inspection of Rotating Equipment at Pase A

# Responsible for:

- Visual Inspection
- Review NDT reports
- Witnessed NDT
- Function Test
- Evaluate and report the result

Cont'd Curriculum Vitae - Wijil Pustiko

# Sucofindo, Batam

Position : Welding Inspector

Inspection of Various Project at Sucofindo Batam

- Visual Inspection
- Review NDT reports
- Witnessed NDT
- Function Test
- Evaluate and report the result

#### 1998 : PT. Kertas Kraft Aceh, Lhokseumawe

Position: Welding Inspector

Inspection and Certification Pressure Vessel

## Responsible for:

- Visual Inspection
- Review Material Test Report
- Verifying that the Manufacturer has a valid Certificate of Authorization and is working to a Quality Control System
- Verifying that the aplicable design calculations are available
- Verifying that materials used in the construction of the vessel comply with the requirement
- Verifying that all welding and brazing procedurres have been qualified
- Making Visual Inspection of Vessel to confirm that there are no material or dimensional defects
- Performing External and Internal inspections and witnessing the hydrostatic or pneumatic test.
- Verifying that the required marking is provided and that any nameplate has been attached to the proper vessel.
- Reporting all inspection during and after finishing the job.

## PT. Semen Andalas Indonesia, Banda Aceh

Position : Inspector

Ultrasonic Test

#### Responsible for:

- Visual Inspection
- Review NDT reports
- Witnessed NDT
- Evaluate and report the result

## 1999 : PT. Pertamina, Rantau Kwala Simpang

Position : Inspector

Inspection and certification Boiler

#### Responsible for:

- Visual Inspection
- Review Material Test Report
- Verifying that the Manufacturer has a valid Certificate of Authorization and is working to a Quality Control System
- Verifying that the aplicable design calculations are available
- Verifying that materials used in the construction of the boiler comply with the requirement
- Verifying that all welding and brazing procedures have been qualified
- Making Visual Inspection of boiler to confirm that there are no material or dimensional defects
- Performing External and Internal inspections and witnessing the hydrostatic or pneumatic test.
- Verifying that the required marking is provided and that any nameplate has been attached to the proper boiler
- Reporting all inspection during and after finishing the job.

Cont'd Curriculum Vitae - Wijil Pustiko

# 2000 : Responsible for Operation Manager the company's bussiness in Industrial and Engineering Services section at Representative, Lhokseumawe.

# PT. Kertas Kraft Aceh, Lhokseumawe

Position: Inspector

Inspection and Certification Boiler

- Visual Inspection
- Review Material Test Report
- Verifying that the Manufacturer has a valid Certificate of Authorization and is working to a Quality Control System
- Verifying that the aplicable design calculations are available

- Verifying that materials used in the construction of the boiler comply with the requirement
- Verifying that all welding and brazing procedures have been qualified
- Making Visual Inspection of boiler to confirm that there are no material or dimensional defects
- Performing External and Internal inspections and witnessing the hydrostatic or pneumatic test.
- Verifying that the required marking is provided and that any nameplate has been attached to the proper boiler
- Reporting all inspection during and after finishing the job.

# PT. Pupuk Iskandar Muda, Lhokseumawe

Position: Inspector

Inspection and Certification Boiler

## Responsible for:

- Visual Inspection
- Review Material Test Report
- Verifying that the Manufacturer has a valid Certificate of Authorization and is working to a Quality Control System
- Verifying that the aplicable design calculations are available
- Verifying that materials used in the construction of the boiler comply with the requirement
- Verifying that all welding and brazing procedures have been qualified
- Making Visual Inspection of boiler to confirm that there are no material or dimensional defects
- Performing External and Internal inspections and witnessing the hydrostatic or pneumatic test.
- Verifying that the required marking is provided and that any nameplate has been attached to the proper boiler
- Reporting all inspection during and after finishing the job.

# 2001 : Responsible for managing the company's bussiness in Industrial and Engineering Services section at Representative, Lhokseumawe.

# Mobil Oil Indonesia Inc., Lhokseumawe

Position : Inspector Inspection of Pipe Line

# Responsible for:

- Visual Inspection
- Witness NDT
- Review NDT Result
- Witness Load Test
- Evaluate and report ther result

Cont'd Curriculum Vitae - Wijil Pustiko

# PT. Semen Andalas Indonesia, Banda Aceh

Position : Inspector

Crane Certification and Boiler Certification

- Visual Inspection
- Review Material Test Report
- Verifying that the Manufacturer has a valid Certificate of Authorization and is working to a Quality Control System
- Verifying that the aplicable design calculations are available
- Verifying that materials used in the construction of the boiler comply with the requirement
- Verifying that all welding and brazing procedures have been qualified
- Making Visual Inspection of boiler to confirm that there are no material or dimensional defects
- Performing External and Internal inspections and witnessing the hydrostatic or

pneumatic test.

- Verifying that the required marking is provided and that any nameplate has been attached to the proper boiler
- Reporting all inspection during and after finishing the job.

# PT. Arun NGL Co, Lhokseumawe

Position: Inspector

Inspection and Recertification Crane

# Responsible for:

- Visual Inspection
- Witness NDT
- Review NDT Result
- Witness Load Test
- Evaluate and report ther result

# 2002 : Responsible for branch manager the company's at Lhokseumawe.

#### Mobil Oil Indonesia Inc., Lhokseumawe

Position : Inspector Coordinator

Inspection of Pipe Line and Recertification of Crane and Pressure Vessel.

#### Responsible for:

- Visual Inspection
- Review Material Test Report
- Verifying that the Manufacturer has a valid Certificate of Authorization and is working to a Quality Control System
- Verifying that the aplicable design calculations are available
- Verifying that materials used in the construction of the vessel comply with the requirement
- Verifying that all welding and brazing procedurres have been qualified
- Making Visual Inspection of Vessel to confirm that there are no material or dimensional defects
- Performing External and Internal inspections and witnessing the hydrostatic or pneumatic test.
- Verifying that the required marking is provided and that any nameplate has been attached to the proper vessel.
- Reporting all inspection during and after finishing the job.

# PT. Samudra Ferro Engineering, Lhokseumawe

Position: Inspector Coordinator

Inspection and Recertification Pressure Vessel

# Cont'd Curriculum Vitae - Wijil Pustiko

# Responsible for:

- Visual Inspection
- Review Material Test Report
- Verifying that the Manufacturer has a valid Certificate of Authorization and is working to a Quality Control System
- Verifying that the aplicable design calculations are available
- Verifying that materials used in the construction of the vessel comply with the requirement
- Verifying that all welding and brazing procedurres have been qualified
- Making Visual Inspection of Vessel to confirm that there are no material or dimensional defects
- Performing External and Internal inspections and witnessing the hydrostatic or pneumatic test.
- Verifying that the required marking is provided and that any nameplate has been attached to the proper vessel.
- Reporting all inspection during and after finishing the job.

## PT. Humpuss Aromatic, Lhokseumawe

Position: Inspector Coordinator Inspection and Recertification Boiler

## Responsible for:

- Visual Inspection
- Review Material Test Report
- Verifying that the Manufacturer has a valid Certificate of Authorization and is working to a Quality Control System
- Verifying that the aplicable design calculations are available
- Verifying that materials used in the construction of the boiler comply with the requirement
- Verifying that all welding and brazing procedures have been qualified
- Making Visual Inspection of boiler to confirm that there are no material or dimensional defects
- Performing External and Internal inspections and witnessing the hydrostatic or pneumatic test.
- Verifying that the required marking is provided and that any nameplate has been attached to the proper boiler
- Reporting all inspection during and after finishing the job.

# 2003 : PT. Samudra Ferro Engineering, Lhokseumawe

Position: Inspector Coordinator

Inspection of Welder Test and Welding Prosedure Specification

## Responsible for:

- Review WPS/WPQ
- Perform welder test
- Witness NDT
- Evaluate and report the result

## 2004 : Mobil Oil Indonesia Inc., Lhokseumawe

Position : Inspector

Inspection of recertification of Pressure Vessel.

# Responsible for:

- Responsible for managing the company's bussiness in Industrial and Engineering Services section at Representative, Lhokseumawe.
- Visual Inspection
- Review Material Test Report
- Verifying that the Manufacturer has a valid Certificate of Authorization and is working to a Quality Control System
- Verifying that the aplicable design calculations are available

#### Cont'd Curriculum Vitae - Wijil Pustiko

- Verifying that materials used in the construction of the vessel comply with the requirement
- Verifying that all welding and brazing procedurres have been qualified
- Making Visual Inspection of Vessel to confirm that there are no material or dimensional defects
- Performing External and Internal inspections and witnessing the hydrostatic or pneumatic test.
- Verifying that the required marking is provided and that any nameplate has been attached to the proper vessel.
- Reporting all inspection during and after finishing the job.

# Mc Dermott, Batam

Position : Inspector

Inspection of recertification Crane

- Visual Inspection
- Witness NDT
- Review NDT Result
- Witness Load Test
- Evaluate and report ther result

## 2005 : PT.Arun NGL Co., Lhokseumawe

Position : Coordinator

Inspection of recertification of Pressure Vessel.

# Responsible for:

- Responsible for managing the company's bussiness in Industrial and Engineering Services section at Representative, Lhokseumawe.
- Visual Inspection
- Review Material Test Report
- Verifying that the Manufacturer has a valid Certificate of Authorization and is working to a Quality Control System
- Verifying that the aplicable design calculations are available
- Verifying that materials used in the construction of the vessel comply with the requirement
- Verifying that all welding and brazing procedurres have been qualified
- Making Visual Inspection of Vessel to confirm that there are no material or dimensional defects
- Performing External and Internal inspections and witnessing the hydrostatic or pneumatic test.
- Verifying that the required marking is provided and that any nameplate has been attached to the proper vessel.

# PT.Arun NGL Co., Lhokseumawe

Position: Inspector

Inspection of recertification of Crane. MIGAS

## Responsible for:

- Visual Inspection
- Review NDT reports
- Witnessed NDT
- Witness Load Test
- Evaluate and report the result

## PT.Sarana Baja Perkasa, Medan

Position : Coordinator

Inspection of recertification of Crane

Cont'd Curriculum Vitae - Wijil Pustiko

# Responsible for:

- Visual Inspection
- Witness NDT
- Review NDT Result
- Witness Load Test
- Evaluate and report ther result

# Doosan Mecatec Co., Ltd. Changwoon - city, Korea

Position : Pressure Vessel Inspector

Inspection of recertification of Pressure Vessel.

- Visual Inspection
- Review Material Test Report
- Verifying that the Manufacturer has a valid Certificate of Authorization and is working to a Quality Control System
- Verifying that the aplicable design calculations are available
- Verifying that materials used in the construction of the vessel comply with the requirement
- Verifying that all welding and brazing procedurres have been qualified
- Making Visual Inspection of Vessel to confirm that there are no material or dimensional defects
- Performing External and Internal inspections and witnessing the hydrostatic or pneumatic test.

 Verifying that the required marking is provided and that any nameplate has been attached to the proper vessel.

# 2005 PT. Tripatra Flour / TF Chevron Maintenance

Position: NDT Project Manager

Responsible for:

- Responsible for managing the company's bussiness in NDT Services section at TF Chevron Maintenance Project , Duri.
- 2006 : Responsible for managing the company's bussiness in Industrial and Engineering Services section at Representative, East Java and Nusa Tenggara
- 2007 : Responsible for managing the company's bussiness in Industrial and Engineering Services section at Representative, East Java and Nusa Tenggara
- 2008 : Responsible for managing the company's bussiness in Industrial and Engineering Services section at Representative, East Java and Nusa Tenggara
- 2009 : Responsible for market managing the company's bussiness in Industrial and Engineering Services section at Representative, East Java and Nusa Tenggara
- 2010 : Responsible for market managing the company's bussiness in Industrial and Engineering Services section at Representative, East Java and West Indonesia
- 2011 Responsible for Project Manager PMU of Integrity QA/QC at Pertamina H E ONWJ 2012
- 2013 Coordinator Project for SKPI (Sertifikasi Kelayakan Penggunaan Instalasi) and SKPP Sertifikasi Kelayakan Penggunaan Peralatan) equipment at Gas Station Unit PT. IPP SPBG Bekasi

Coordinator Project for SKPI (Sertifikasi Kelayakan Penggunaan Instalasi) and SKPP Sertifikasi Kelayakan Penggunaan Peralatan) equipment at Gas Separator Unit PT. Exterran Indonesia Banyu Urip Bojonegoro

Cont'd Curriculum Vitae - Wijil Pustiko

- 2014 Coordinator Project for SKPI (Sertifikasi Kelayakan Penggunaan Instalasi) and SKPP Sertifikasi Kelayakan Penggunaan Peralatan) equipment at Gas Seperator Unit PT. Exterran Indonesia Senipah Kalimantan Timur
- 2015 Coordinator Certification equipment for operation permit of HUBLA and Depnaker of STS , CC crane at Teluk Lamong Port PT. Pelindo III

# QA/QC inspector for fabricate ARTG crane PT. Pelindo III at Kone Dalian Workshop China Responsible for:

- Visual Inspection
- Review Material Test Report
- Verifying that the Manufacturer has a valid Certificate of Authorization and is working to a Quality Control System
- Verifying that the aplicable design calculations are available
- Verifying that materials used in the construction of the vessel comply with the requirement
- Verifying that all welding, brazing and paintingprocedurres have been qualified
- Making Visual Inspection of Crane to confirm that there are no material or dimensional defects
- Performing External and Internal inspections and witnessing the pneumatic
- Verifying that the required marking is provided and that any nameplate has been attached to the proper Crane.

# 2016 QA/QC inspector for fabricate RTG crane PT. Pelindo IV at RainbowCartage China Responsible for:

- Visual Inspection
- Review Material Test Report

- Verifying that the Manufacturer has a valid Certificate of Authorization and is working to a Quality Control System
- Verifying that the aplicable design calculations are available
- Verifying that materials used in the construction of the vessel comply with the requirement
- Verifying that all welding, brazing and paintingprocedurres have been qualified
- Making Visual Inspection of Crane to confirm that there are no material or dimensional defects
- Performing External and Internal inspections and witnessing the pneumatic
- Verifying that the required marking is provided and that any nameplate has been attached to the proper Crane.

2017 - 2019

Responsible for Department Head of Technical and General Commodity services at Samarinda Branch

2019 - 2020

Responsible for Department Head of Marketing at Surabaya Brach

2020 - 2021

Responsible for Department Head of Commodity and Trade Solutions at Surabaya Branch

2022 - 2023

Responsible for General Manager at Padang Branch

2023 until now

**Carry out the Retirement Preparation Period** 

I the undersign certify that to the best my knowledge and belief, the bio data contained in this CV correctly describe my self, my qualifications and my expertise.

Surabaya, January 24, 2024

**WIJIL PUSTIKO**